

## 2.2.8 Sea Turtle Report Log

### SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: mobile CONTRACT NO.: W 91278-04-C-0022  
VESSEL NAME: stuvistant FIRM NAME: Bear stuvistant  
LOAD NUMBER: 43 LOADING START TIME (24 HR): 1330 DATE: 4-15-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds Variable 10 knots, seas 2-3  
WATERWAY TEMP (°F): SURFACE: — MID-DEPTH TO WATER BOTTOM: —

#### SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW: —  
PORT SCREEN CONTENTS: wood, trash, blue crabs

STARBOARD SCREEN CONTENTS: same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

#### COMMENTS AND OBSERVATIONS:

300700-260700  
observer aboard 1425, 1st load coastwise consulting

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: —

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: —

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westergaard

OBSERVER'S SIGNATURE: [Signature]

#### DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: —  
HEAD WIDTH: — PLASTRON LENGTH: —  
CARAPACE S.L. LENGTH: — CARAPACE S. L. WIDTH: —  
CARAPACE O.C. LENGTH: — CARAPACE O.C. WIDTH: —  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: —

TAG DATE: — TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: —

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Stevens FIRM NAME: Dean Stevens  
LOAD NUMBER: 44 LOADING START TIME (24 HR): 2113 DATE: 8-15-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds variable 10 knots seas 2-3  
WATERWAY TEMP (°F): SURFACE: 64 MID-DEPTH TO WATER BOTTOM: 63

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW:       

PORT SCREEN CONTENTS: wood, trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS:

300700 260700

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:       

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:       

HEAD WIDTH:        PLASTRON LENGTH:       

CARAPACE S.L. LENGTH:        CARAPACE S. L. WIDTH:       

CARAPACE O.C. LENGTH:        CARAPACE O.C. WIDTH:       

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:       

TAG DATE:        TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile channel CONTRACT NO.: W 91278-04-G-0632  
VESSEL NAME: Stuyvesant FIRM NAME: Bican - Stuyvesant  
LOAD NUMBER: 43 LOADING START TIME (24 HR): 0412 DATE: 14-16-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10-15 knots, seas 2-4'  
WATERWAY TEMP (°F): SURFACE: 65 MID-DEPTH TO WATER BOTTOM: 64'

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Wood trash

STARBOARD SCREEN CONTENTS: same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 300+00 - 260 fcp  
1420 30' 09 426 N 80' 08 223 W 680'

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

## 2.2.8 Sea Turtle Report Log

### SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Bray-Stuyvesant  
LOAD NUMBER: 46 LOADING START TIME (24 HR): 1116 DATE: 4-16-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10-15 knots, seas 2-3  
WATERWAY TEMP (°F): SURFACE: 67 MID-DEPTH TO WATER BOTTOM: 66

#### SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: wood, trash

STARBOARD SCREEN CONTENTS: same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: H20 20' 36.530N 88° 01.932W 1118  
300+00 - 260+00

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: Eric Westerman

#### DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Stevensant FIRM NAME: 13can Stevensant  
LOAD NUMBER: 47 LOADING START TIME (24 HR): 1821 DATE: 9-16-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 15 knots, Seas 2-4'  
WATERWAY TEMP (°F): SURFACE: 69.2 MID-DEPTH TO WATER BOTTOM: 68.1

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: \_\_\_\_\_

STARBOARD SCREEN CONTENTS: Some

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120 1123 30 36 58 9A 98 01 94SW  
300'00 - 260'00

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile CONTRACT NO: W 91278-04-C-0022  
VESSEL NAME: Stevensant FIRM NAME: Beaumont Stevensant  
LOAD NUMBER: 48 LOADING START TIME (24 HR): 0115 DATE: 4-17-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Windy 15 knots SWS 2  
WATERWAY TEMP (°F): SURFACE: 69 MID-DEPTH TO WATER BOTTOM: 68

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: V OVER-FLOW: \_\_\_\_\_

PORT SCREEN CONTENTS: Wood, trash

STARBOARD SCREEN CONTENTS: SAMP

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES \_\_\_\_\_ NO ☒

COMMENTS AND OBSERVATIONS: 300000 - 260 FCB  
1720 30 09 202 88 07 6065

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: mobile channel CONTRACT NO: W 91278-04-C  
VESSEL NAME: stuyvesant FIRM NAME: Bran Stuyvesant  
LOAD NUMBER: 49 LOADING START TIME (24 HR): 0812 DATE: 4-17-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: good  
WEATHER CONDITIONS: Winds 15 knots, S 957.3  
WATERWAY TEMP (°F): SURFACE: 68 MID-DEPTH TO WATER BOTTOM: 67

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW:       

PORT SCREEN CONTENTS: wood, trash

STARBOARD SCREEN CONTENTS: same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 320'00" 260'00"  
1720 30° 36.593 88° 01' 44.00" 813

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:       

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: no

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC WESTERMAN

OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:       

HEAD WIDTH:       

PLASTRON LENGTH:       

CARAPACE S.L. LENGTH:       

CARAPACE S. L. WIDTH:       

CARAPACE O.C. LENGTH:       

CARAPACE O.C. WIDTH:       

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:       

TAG DATE:        TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile CONTRACT NO: W 91278-04-4-0021  
VESSEL NAME: Stavvisant FIRM NAME: Beaumont Stavvisant  
LOAD NUMBER: 50 LOADING START TIME (24 HR): 1525 DATE: 4-17-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 15 knots, Seas 2-3  
WATERWAY TEMP (°F): SURFACE: 70 MID-DEPTH TO WATER BOTTOM: 69

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: wood, trash

STARBOARD SCREEN CONTENTS: same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 300KCO-260700  
H20 30 36 507N 88°01.886W 1525

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_



2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Starvissant FIRM NAME: Bras Starvissant  
LOAD NUMBER: 51 LOADING START TIME (24 HR): 2224 DATE: 4-17-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Windy 15 knots, seas 7-8  
WATERWAY TEMP (°F): SURFACE: 69 MID-DEPTH TO WATER BOTTOM: 68

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 300 JOW-260TCU  
300 C9 281A RF OF 037W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman  
OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Beaumont-Stuyvesant  
LOAD NUMBER: 52 LOADING START TIME (24 HR): 0555 DATE: 4-18-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10 knots, seas 1-3'  
WATERWAY TEMP (°F): SURFACE: 70 MID-DEPTH TO WATER BOTTOM: 69

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Clay, mud

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 300100-260100  
30 09 297N 8800 004W 457

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile CONTRACT NO: W 91278-04-C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: 13can stuyvesant  
LOAD NUMBER: 53 LOADING START TIME (24 HR): 1259 DATE: 5-18-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: GOOD  
WEATHER CONDITIONS: Winds 10 knots, seas 1-2'  
WATERWAY TEMP (°F): SURFACE: 72 MID-DEPTH TO WATER BOTTOM: 71

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Clay, wood, trash

STARBOARD SCREEN CONTENTS: same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 300' to 260' to 120' 36.560 8801 881 1259

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman  
OBSERVER'S SIGNATURE: eric westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile CONTRACT NO: L191278-04-C-0022  
VESSEL NAME: Starvesant FIRM NAME: Beaumont Starvesant  
LOAD NUMBER: 54 LOADING START TIME (24 HR): 1956 DATE: 5-18-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10 knots, seas 1-3  
WATERWAY TEMP (°F): SURFACE: 72 MID-DEPTH TO WATER BOTTOM: 71

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Clay, Wood, Trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 300+00 - 260+00  
1120 30 36 596 8801925 1956

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC WESTRICH

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_

PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_

CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_

CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐

DEAD: ☐

INJURED: ☐

OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: mobile CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: stuyvesant FIRM NAME: Boon stuyvesant  
LOAD NUMBER: 55 LOADING START TIME (24 HR): 0309 DATE: 4-19-04  
DRAGHEAD DEFLECTOR USED? YES/ NO DEFLECTOR CONDITION: good  
WEATHER CONDITIONS: Winds 7-10 knots sea 1-2  
WATERWAY TEMP (°F): SURFACE: 71 MID-DEPTH TO WATER BOTTOM: 70

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW: \_\_\_\_\_

PORT SCREEN CONTENTS: clay, wood, trash

STARBOARD SCREEN CONTENTS: same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES \_\_\_\_\_ NO V

COMMENTS AND OBSERVATIONS: 200+00 - 260+00  
1720 30 09 231 8807 682

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: ERIC Westman

OBSERVER'S SIGNATURE: Eric Westman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile CONTRACT NO: W 91278-04-C-0022  
VESSEL NAME: Stavvrsant FIRM NAME: Bray Stavvrsant  
LOAD NUMBER: 56 LOADING START TIME (24 HR): 1020 DATE: 9-19-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10 knots, seas 1-2  
WATERWAY TEMP (°F): SURFACE: 72 MID-DEPTH TO WATER BOTTOM: 71

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Clay, wood, trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 300 + 00 260 HU  
30 36 55 IN 88 01 88 3 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westman  
OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile CONTRACT NO: W91278-04-C10022  
VESSEL NAME: Stapvissant FIRM NAME: Beaumont Stapvissant  
LOAD NUMBER: 57 LOADING START TIME (24 HR): 1747 DATE: 4-19-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 70 knots seas 1-2  
WATERWAY TEMP (°F): SURFACE: 72 MID-DEPTH TO WATER BOTTOM: 71

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: V OVER-FLOW:   
PORT SCREEN CONTENTS: clay, trash, weed

STARBOARD SCREEN CONTENTS: same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 300400-260400  
3036 026N 88°01' 941W 1952

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:   
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman  
OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:   
HEAD WIDTH:  PLASTRON LENGTH:   
CARAPACE S.L. LENGTH:  CARAPACE S. L. WIDTH:   
CARAPACE O.C. LENGTH:  CARAPACE O.C. WIDTH:   
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:   
TAG DATE:  TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Beaumont Stuyvesant  
LOAD NUMBER: 58 LOADING START TIME (24 HR): 0131 DATE: 9-20-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10-15 knots, Seas 2-3  
WATERWAY TEMP (°F): SURFACE: 77 MID-DEPTH TO WATER BOTTOM: 72

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: crab trap, clay, weed, trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 300+00 - 260+00  
H20 30 09 281N 88 07. 845W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: No

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_



2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: U91278-04-C-0022  
VESSEL NAME: STAYVUSANT FIRM NAME: BRAD STAYVUSANT  
LOAD NUMBER: 59 LOADING START TIME (24 HR): 0843 DATE: 8-24-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS TURBULENCE, SEA 1-2  
WATERWAY TEMP (°F): SURFACE: 73 MID-DEPTH TO WATER BOTTOM: 72

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐  
PORT SCREEN CONTENTS: Clay, wood, trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 300' NO - 260' + 60'  
30' 36 581 N 88' 01 943 V 814

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIK WESTERMAN  
OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: mobile channel CONTRACT NO: W91278-04-F-0022  
VESSEL NAME: Stewart FIRM NAME: Bran Stewart  
LOAD NUMBER: 60 LOADING START TIME (24 HR): 1354 DATE: 4-20-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: good  
WEATHER CONDITIONS: Windy 10 knots, seas 2-3  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Trash, wood

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: NEW AREA 1120+00 - 1160+00  
1720 30 22 56 W 8801261W 1354

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC WESTERMAN

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

## 2.2.8 Sea Turtle Report Log

### SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile channel CONTRACT NO: W 91278-04-C-0002  
VESSEL NAME: Starvesant FIRM NAME: Beach Starvesant  
LOAD NUMBER: 67 LOADING START TIME (24 HR): 1800 DATE: 4-20-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: GOOD  
WEATHER CONDITIONS: Winds 10-15 knots, seas 2-3  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

#### SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐  
PORT SCREEN CONTENTS: \_\_\_\_\_

STARBOARD SCREEN CONTENTS: same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00-1160+00  
H2O 30 22 365 N 80 1294 W 1807

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Eric Westerman

OBSERVER'S SIGNATURE: Eric Westerman

#### DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile channel CONTRACT NO: W 91278-04-C-0002  
VESSEL NAME: Stewart FIRM NAME: Boon Stewart  
LOAD NUMBER: 62 LOADING START TIME (24 HR): 2241 DATE: 4-20-94  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 15 knots, seas 2-3'  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73'

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐  
PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 1720 + 00 - 1764 + 00  
1720 1807 3022 3650 8801 2940 1807

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman  
OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

## 2.2.8 Sea Turtle Report Log

### SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile channel CONTRACT NO: W91278-04-C-002  
VESSEL NAME: Stevensant FIRM NAME: Beach Stevensant  
LOAD NUMBER: 63 LOADING START TIME (24 HR): 308 DATE: 4-21-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 15 knots, Seas 2-3  
WATERWAY TEMP (°F): SURFACE: 72 MID-DEPTH TO WATER BOTTOM: 72

#### SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ✓ OVER-FLOW: \_\_\_\_\_  
PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES \_\_\_\_\_ NO ☒

COMMENTS AND OBSERVATIONS: 1120700-1160+00  
1120 3008 308N 88 06 90W 530

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: ERIC W. Sterman  
OBSERVER'S SIGNATURE: [Signature]

#### DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile channel CONTRACT NO: W91278-04-C-002  
VESSEL NAME: Stewart FIRM NAME: Beck Stewart  
LOAD NUMBER: 64 LOADING START TIME (24 HR): 714 DATE: 9-21-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Windy is knots, sea 2-4'  
WATERWAY TEMP (°F): SURFACE: 72 MID-DEPTH TO WATER BOTTOM: 71

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: V OVER-FLOW: \_\_\_\_\_  
PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES \_\_\_\_\_ NO ☒  
COMMENTS AND OBSERVATIONS: 111200' 1160+00  
1120 3009 913N 88 08 15W 1000

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: ERIK Westerman  
OBSERVER'S SIGNATURE: Erik Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Sturvesant FIRM NAME: Mean-Sturvesant  
LOAD NUMBER: 65 LOADING START TIME (24 HR): 1204 DATE: 4-21-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 15 knots, seas 2-4'  
WATERWAY TEMP (°F): SURFACE: 72 MID-DEPTH TO WATER BOTTOM: 72

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Trash, crab trap

STARBOARD SCREEN CONTENTS: same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 111200-116000  
1420 30'09 226N 88°07'96W 1428

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NV

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile channel CONTRACT NO: W 91278-04-G-0022  
VESSEL NAME: Sturgesant FIRM NAME: Sturgesant  
LOAD NUMBER: 86 LOADING START TIME (24 HR): 1617 DATE: 4-21-04  
DRAGHEAD DEFLECTOR USED? YES/ NO DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: wind 15 knots, seas 3-5  
WATERWAY TEMP (°F): SURFACE: 73 MID-DEPTH TO WATER BOTTOM: 72

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ✓ OVER-FLOW: \_\_\_\_\_

PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: Samt

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES \_\_\_\_\_ NO ✓  
COMMENTS AND OBSERVATIONS: 111204CC - 11604CC  
19201428 30 09 226N 8807 968W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: ERIC WESTERMAN  
OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_



## 2.2.8 Sea Turtle Report Log

### SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile channel CONTRACT NO: W91278-04-C-0002  
VESSEL NAME: Stewart FIRM NAME: Boon Stewart  
LOAD NUMBER: 67 LOADING START TIME (24 HR): 2026 DATE: 4-21-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 15+ knots seas 3-5  
WATERWAY TEMP (°F): SURFACE: 73 MID-DEPTH TO WATER BOTTOM: 22

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Trash shell

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1720 to 1160 + 60

4230 09 264N 88 00 135W 240

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: NW

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NW

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: FRY Western

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_

PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_

CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_

CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐

DEAD: ☐

INJURED: ☐

OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☒ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_

TURTLE RELEASED WITH TAG? YES: ☐

NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: mobile channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Bran Stuyvesant  
LOAD NUMBER: 58 LOADING START TIME (24 HR): 0040 DATE: 4-22-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 15 knots seas 2-4  
WATERWAY TEMP (°F): SURFACE: 77 MID-DEPTH TO WATER BOTTOM: 72

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: V OVER-FLOW: \_\_\_\_\_

PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES \_\_\_\_\_ NO ☒

COMMENTS AND OBSERVATIONS: 1120700 - 1160700  
1420 2240 3009 26KN 13SW

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: N/A

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Brian Stuyvesant  
LOAD NUMBER: 69 LOADING START TIME (24 HR): 0858 DATE: 4-22-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 15 knots, Seas 2-4'  
WATERWAY TEMP (°F): SURFACE: 72 MID-DEPTH TO WATER BOTTOM: 72

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120100-1166700  
1720 124 30 09 275 88 08 082

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: NV

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NV

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Edgar Westerman

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile channel CONTRACT NO: W91278-09-C-0022  
VESSEL NAME: STANVISANT FIRM NAME: Dean Stanvisant  
LOAD NUMBER: 70 LOADING START TIME (24 HR): 0914 DATE: 4-22-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: GOOD  
WEATHER CONDITIONS: WIND 15 KNOTS, SEAS 2-3  
WATERWAY TEMP (°F): SURFACE: 72 MID-DEPTH TO WATER BOTTOM: 71

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Trash, weed

STARBOARD SCREEN CONTENTS: SAMI

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120TCU-1160TCU  
1720 1130 30 09 258N 8808042W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: NO

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W 91278-04-C-0022  
VESSEL NAME: Stevens FIRM NAME: Beck Stevens  
LOAD NUMBER: 11 LOADING START TIME (24 HR): 1323 DATE: 9-22-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 15 knots, SWS 3.5  
WATERWAY TEMP (°F): SURFACE: 73 MID-DEPTH TO WATER BOTTOM: 72

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: Y OVER-FLOW:       

PORT SCREEN CONTENTS: trash

STARBOARD SCREEN CONTENTS: SAME  
1120 1130 30 09 258N 88 04 042

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 1120 + 00 - 1160 + 00

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:         
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES:        NO:       

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman  
OBSERVER'S SIGNATURE: ERIC Westerman

DATA ON TURTLES RETAINED IN HOPPER:  
SPECIES:         
HEAD WIDTH:        PLASTRON LENGTH:         
CARAPACE S.L. LENGTH:        CARAPACE S. L. WIDTH         
CARAPACE O.C. LENGTH:        CARAPACE O.C. WIDTH         
SPECIMEN CONDITION: ALIVE:        DEAD:        INJURED:        OTHER:       

TURTLE INITIALLY TAGGED? YES:        NO:        TAG NO:         
TAG DATE:        TURTLE RELEASED WITH TAG? YES:        NO:         
COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W 91278-04-C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: 13047 Stuyvesant  
LOAD NUMBER: 12 LOADING START TIME (24 HR): 1901 DATE: 4-22-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 13 knots, seas 3'5"  
WATERWAY TEMP (°F): SURFACE: 72 MID-DEPTH TO WATER BOTTOM: 71

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: V OVER-FLOW: \_\_\_\_\_  
PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: SMC

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES \_\_\_\_\_ NO \_\_\_\_\_

COMMENTS AND OBSERVATIONS: 1120 + 00 + 1160 + 0  
1720 3008 862N 8807186W 2110

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W 91278-04-C-0022  
VESSEL NAME: Stump & Sargent FIRM NAME: 13 Can Stump & Sargent  
LOAD NUMBER: 73 LOADING START TIME (24 HR): 2310 DATE: 4-23-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 15 knots, seas 3' S  
WATERWAY TEMP (°F): SURFACE: 73 MID-DEPTH TO WATER BOTTOM: 72

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: V OVER-FLOW: \_\_\_\_\_  
PORT SCREEN CONTENTS: Trash, Kay

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES \_\_\_\_\_ NO ☒  
COMMENTS AND OBSERVATIONS: 1120 + 00 - 1160 + 00  
1720 3008 862N 88 07 186W 2110

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman  
OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: mobile channel CONTRACT NO: W 91278-04-C-0022  
VESSEL NAME: stevedorant FIRM NAME: McGraw-Hill Construction  
LOAD NUMBER: 74 LOADING START TIME (24 HR): 325 DATE: 9-23-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10-15 knots, S 19, 2-4  
WATERWAY TEMP (°F): SURFACE: 73 MID-DEPTH TO WATER BOTTOM: 72

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: V OVER-FLOW: \_\_\_\_\_

PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES \_\_\_\_\_ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00-1760+00  
42130 09 276 02 880 000

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_



2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Stewart FIRM NAME: Beaumont-Stewart  
LOAD NUMBER: 75 LOADING START TIME (24 HR): 725 DATE: 4-23-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Windy 10 knots, Seas 2-4  
WATERWAY TEMP (°F): SURFACE: 75 MID-DEPTH TO WATER BOTTOM: 74

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120740-1160740  
1720 0955 30' 08 945N 88° 07 476W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: NU

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NU

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Eric Westerman

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: mobile channel CONTRACT NO: 6191278-04-C-0022  
VESSEL NAME: Sturvesant FIRM NAME: Beck Sturvesant  
LOAD NUMBER: 76 LOADING START TIME (24 HR): 1149 DATE: 4-23-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: GOOD  
WEATHER CONDITIONS: WINDS 10-15 knots, seas 2-4  
WATERWAY TEMP (°F): SURFACE: 75 MID-DEPTH TO WATER BOTTOM: 74

SCREEN WATCH: ☒

SCREEN TYPE: IN-FLOW:                      OVER-FLOW:                     

PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00+1160  
1720 1144 30° 22' 14S N 88° 01' 35S W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:                     

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NONE

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kimberly Peters

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:                     

HEAD WIDTH:                      PLASTRON LENGTH:                     

CARAPACE S.L. LENGTH:                      CARAPACE S. L. WIDTH:                     

CARAPACE O.C. LENGTH:                      CARAPACE O.C. WIDTH:                     

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:                     

TAG DATE:                      TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Shuywernt FIRM NAME: Bea Shuywernt  
LOAD NUMBER: 77 LOADING START TIME (24 HR): 1603 DATE: 4.23.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS 10-15 SE - SEAS 2-4'  
WATERWAY TEMP (°F): SURFACE: 75 MID-DEPTH TO WATER BOTTOM: 74

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐  
PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120 + 00 + 1160  
HLC 1610 30° 22' 46.43 N 88° 01' 31.57 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kimberly Peters

OBSERVER'S SIGNATURE: Kimberly Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S.L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Star Channel FIRM NAME: Bay Star Marine  
LOAD NUMBER: 78 LOADING START TIME (24 HR): 2014 DATE: 4-23-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS 10-15 SE, SWS 2-4  
WATERWAY TEMP (°F): SURFACE: 75 MID-DEPTH TO WATER BOTTOM: 74

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00t/60  
1120/1937 30°23' C 197°N 88°01.2365 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: NO

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kimberly Peters  
OBSERVER'S SIGNATURE: Kimberly Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Surveyor FIRM NAME: Bechtel Survey  
LOAD NUMBER: 79 LOADING START TIME (24 HR): 0018 DATE: 4-24-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds T-10 knots, seas 2-3  
WATERWAY TEMP (°F): SURFACE: 75 MID-DEPTH TO WATER BOTTOM: 74

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00-1760+00  
1720 30 22 455N 88 01 321 W 0018

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: NO

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman  
OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: STUNCSANT FIRM NAME: Dean Stunvant  
LOAD NUMBER: 80 LOADING START TIME (24 HR): 0425 DATE: 4-24-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Windy, cloudy, 50-55°F  
WATERWAY TEMP (°F): SURFACE: 75 MID-DEPTH TO WATER BOTTOM: 74

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Dead ray trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00 - 1160+00  
H20 30 22 990 N 88 01 250 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W 91278-09-1-0022  
VESSEL NAME: Staplesant FIRM NAME: Bray - Staplesant  
LOAD NUMBER: 81 LOADING START TIME (24 HR): 151 DATE: 4-24-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10 knots, fog 5-452-4  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: \_\_\_\_\_

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120700-1160700  
H20 30° 22' 47" N 88° 01' 27" W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Eric Westerman  
OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W 91278-09-C-0022  
VESSEL NAME: Stumpson FIRM NAME: Bran-Stumpson  
LOAD NUMBER: 82 LOADING START TIME (24 HR): 1255 DATE: 4-24-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS SE 10-15 KTS SEAS 2-4'  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: TRASH

STARBOARD SCREEN CONTENTS: TRASH

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00 - 1160+00  
420 30° 22.521 N 88° 01.296 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:                     

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kimberly Peters  
OBSERVER'S SIGNATURE: Kimberly Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:                       
HEAD WIDTH:                      PLASTRON LENGTH:                       
CARAPACE S.L. LENGTH:                      CARAPACE S. L. WIDTH:                       
CARAPACE O.C. LENGTH:                      CARAPACE O.C. WIDTH:                       
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:                     

TAG DATE:                      TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:



2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04C-0022  
VESSEL NAME: SHUYVESANT FIRM NAME: Beau Shuyvesant  
LOAD NUMBER: 83 LOADING START TIME (24 HR): 1651 DATE: 4-24-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS SE 15 KTS SEAS 3-4'  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: TRASH

STARBOARD SCREEN CONTENTS: TRASH

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00-1160+00  
1120 30° 22.591' N 88° 07.243' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kimberly Peters  
OBSERVER'S SIGNATURE: Kimberly Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W 91278-04-C0022  
VESSEL NAME: Sam S. Myerant FIRM NAME: Sam S. Myerant  
LOAD NUMBER: 84 LOADING START TIME (24 HR): 2052 DATE: 4-24-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS 15 KTS SEAS 2-4  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐  
PORT SCREEN CONTENTS: TRASH

STARBOARD SCREEN CONTENTS: TRASH

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 1120+00-1160+00  
HL 30° 22.530 N 88° 06'-252 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kimberly Peters  
OBSERVER'S SIGNATURE: Kimberly Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W 91278-04-C-0022  
VESSEL NAME: STUYVESANT FIRM NAME: Bechtel Stuyvesant  
LOAD NUMBER: 85 LOADING START TIME (24 HR): 0102 DATE: 4-25-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds to 15 knots, seas 2-4'  
WATERWAY TEMP (°F): SURFACE: 75 MID-DEPTH TO WATER BOTTOM: 74

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐  
PORT SCREEN CONTENTS: Trash, wood

STARBOARD SCREEN CONTENTS: same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00-1160+00  
1720 30 22 246N, 8801315W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W191278 04-C10022  
VESSEL NAME: Stuyvesant FIRM NAME: Bran Stuyvesant  
LOAD NUMBER: 86 LOADING START TIME (24 HR): 0506 DATE: 4-25-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10-15 knots seas 2-4'  
WATERWAY TEMP (°F): SURFACE: 75 MID-DEPTH TO WATER BOTTOM: 74

SCREEN WATCH: ☒

SCREEN TYPE: IN-FLOW:                      OVER-FLOW:                     

PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00-1160+00  
1120 30 22 289 88 01 312

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:                     

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:                       
HEAD WIDTH:                      PLASTRON LENGTH:                       
CARAPACE S.L. LENGTH:                      CARAPACE S. L. WIDTH:                       
CARAPACE O.C. LENGTH:                      CARAPACE O.C. WIDTH:                       
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:                     

TAG DATE:                      TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: mobile channel CONTRACT NO: 191278-04-C-0022  
VESSEL NAME: Stavvissant FIRM NAME: Bras-Stavvissant  
LOAD NUMBER: 87 LOADING START TIME (24 HR): 0916 DATE: 4-25-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: GOOD  
WEATHER CONDITIONS: Winds 10 knots Seas 2-3  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00-1160+00  
1420 30 22 #66N 8801 319W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: 4/91278-04-C-0022  
VESSEL NAME: Starvickant FIRM NAME: Bran-Stevickant  
LOAD NUMBER: 88 LOADING START TIME (24 HR): 1319 DATE: 4-25-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WIND 10-20 KTS SWS 2-3 -  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: TRASH, weeds

STARBOARD SCREEN CONTENTS: TRASH

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00 - 1760+00  
H2O 30° 22.759N 88° 01.264W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kimberly Peters

OBSERVER'S SIGNATURE: Kimberly Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Dean Stuyvesant  
LOAD NUMBER: 87 LOADING START TIME (24 HR): 1726 DATE: 4-25-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION:             
WEATHER CONDITIONS: WIND 10-20 KTS SEA 2-3'  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: TRASH

STARBOARD SCREEN CONTENTS: TRASH

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120400-116000

1720 30°22.573N 88°01.291W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:           

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kimberly Peters

OBSERVER'S SIGNATURE: Kimberly Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:           

HEAD WIDTH:            PLASTRON LENGTH:           

CARAPACE S.L. LENGTH:            CARAPACE S. L. WIDTH:           

CARAPACE O.C. LENGTH:            CARAPACE O.C. WIDTH:           

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:           

TAG DATE:            TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Seymour FIRM NAME: Rean & Longwood  
LOAD NUMBER: 90 LOADING START TIME (24 HR): 2130 DATE: 4-25-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: GOOD  
WEATHER CONDITIONS: WINDS 10-15 KTS 2-4  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐  
PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00 - 1160+00

172° 30° 22.687 N 88° 01.280 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kimberly Reed

OBSERVER'S SIGNATURE: Kimberly Reed

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_



2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile channel CONTRACT NO: U91278-04-C-0022  
VESSEL NAME: Sturgeson FIRM NAME: Sturgeson + Ryan  
LOAD NUMBER: 91 LOADING START TIME (24 HR): 137 DATE: 4-26-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS 10-15 knots, rain, seas 2-4  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐  
PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120700-1160700  
1720 30 22 904N 84 01 247W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: N/A  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman  
OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04-C002  
VESSEL NAME: STUNNISON FIRM NAME: STUNNISON - Bean  
LOAD NUMBER: 92 LOADING START TIME (24 HR): 528 DATE: 9-26-04  
DRAGHEAD DEFLECTOR USED? YES ☐ NO ☒ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10 knots, Seas 2-4  
WATERWAY TEMP (°F): SURFACE: 77 MID-DEPTH TO WATER BOTTOM: 76

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Trash, clay

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120700-1160400  
H20 30 23 020 88°01'198L

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:                     

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: FRY W. C. Feiman

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:                     

HEAD WIDTH:                      PLASTRON LENGTH:                     

CARAPACE S.L. LENGTH:                      CARAPACE S. L. WIDTH:                     

CARAPACE O.C. LENGTH:                      CARAPACE O.C. WIDTH:                     

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:                     

TAG DATE:                      TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: mobile channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: stuyversant FIRM NAME: Began-Stuyversant  
LOAD NUMBER: 93 LOADING START TIME (24 HR): 958 DATE: 4-26-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10 knots seas 2-4  
WATERWAY TEMP (°F): SURFACE: 77 MID-DEPTH TO WATER BOTTOM: 76

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐  
PORT SCREEN CONTENTS: TRASH & clay

STARBOARD SCREEN CONTENTS: TRASH & clay

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 1120700-1160700  
1720 30 23 009088 011924

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kimberly Bares  
OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

## 2.2.8 Sea Turtle Report Log

### SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W-78-04-C-0001  
VESSEL NAME: Stuyvesant FIRM NAME: San Stuyvesant  
LOAD NUMBER: 94 LOADING START TIME (24 HR): 1432 DATE: 4-26-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION:             
WEATHER CONDITIONS: WINDS 12-15/045-50KTS  
WATERWAY TEMP (°F): SURFACE: 77 MID-DEPTH TO WATER BOTTOM: 76

#### SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: TRASH & Clay

STARBOARD SCREEN CONTENTS: TRASH & Clay

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1130+00-1140+00

420 30° 22.959'N 88° 01' 25.2'W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:           

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kimberly Peters

OBSERVER'S SIGNATURE: Kimberly Peters

#### DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:           

HEAD WIDTH:           

PLASTRON LENGTH:           

CARAPACE S.L. LENGTH:           

CARAPACE S. L. WIDTH:           

CARAPACE O.C. LENGTH:           

CARAPACE O.C. WIDTH:           

SPECIMEN CONDITION: ALIVE: ☐

DEAD: ☐

INJURED: ☐

OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:           

TAG DATE:           

TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

## SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Syrusant FIRM NAME: Beaumont  
LOAD NUMBER: 96 LOADING START TIME (24 HR): 2300 DATE: 4-27-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS 10-15 KTS SEAS 2-3'  
WATERWAY TEMP (°F): SURFACE: 77 MID-DEPTH TO WATER BOTTOM: 76

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Trash, clay

STARBOARD SCREEN CONTENTS: same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00-1160+00

H20 30°22.0'0" N 88° 01.189

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: WIT

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: WIT

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIK Westerman

OBSERVER'S SIGNATURE: ERIK Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Beaumont Stevedoring  
LOAD NUMBER: 97 LOADING START TIME (24 HR): 315 DATE: 4-27-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Windy 10 knots seas 2-4'  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Clay, trash

STARBOARD SCREEN CONTENTS: same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00-1160+00  
H2O 30 23 265N PR 01 15 74

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: NO

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Starvcsant FIRM NAME: Bran-Starvcsant  
LOAD NUMBER: 98 LOADING START TIME (24 HR): 713 DATE: 4-27-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10-15 knots, Seas 2-3  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: Trash, clay

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120 to 1160 to 1172  
9120 30 23 080N88 01 172

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC W. Sterman

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_



2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: STUYVESANT FIRM NAME: Bran Stuyvesant  
LOAD NUMBER: 99 LOADING START TIME (24 HR): 1143 DATE: 4-27-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10 knots, seas 2-3  
WATERWAY TEMP (°F): SURFACE: 77 MID-DEPTH TO WATER BOTTOM: 76

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: TRASH, clay

PINS pulled on this load to clean hopper cage  
STARBOARD SCREEN CONTENTS: SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120 to 1760

H20 30 23 079N 88 01 72 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: No

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kimberly Reese

OBSERVER'S SIGNATURE: Kimberly Reese

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Brian Stuyvesant  
LOAD NUMBER: 100 LOADING START TIME (24 HR): 1553 DATE: 4-27-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: \_\_\_\_\_  
WEATHER CONDITIONS: WINDS 10/15 SWS-23'  
WATERWAY TEMP (°F): SURFACE: 77 MID-DEPTH TO WATER BOTTOM: 76

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW: \_\_\_\_\_

PORT SCREEN CONTENTS: Clear

STARBOARD SCREEN CONTENTS: 1120+00-1160+00

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES \_\_\_\_\_ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00-1160+00  
PLD 30° 23.395 N 88° 01.788 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: Kimberly Peters  
OBSERVER'S SIGNATURE: Kimberly Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Becon Stuyvesant  
LOAD NUMBER: 101 LOADING START TIME (24 HR): 2017 DATE: 4-27-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION:             
WEATHER CONDITIONS: WINDS 10 KTS SEAS 2-3  
WATERWAY TEMP (°F): SURFACE: 77 MID-DEPTH TO WATER BOTTOM: 76

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW:             
PORT SCREEN CONTENTS:           

MMD

STARBOARD SCREEN CONTENTS:           

MMD

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120 +00 - 1160 +00  
HCO 30° 23.381 N 88° 01.182 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:           

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kimberly Rexer

OBSERVER'S SIGNATURE: Kimberly Rexer

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:           

HEAD WIDTH:            PLASTRON LENGTH:           

CARAPACE S.L. LENGTH:            CARAPACE S. L. WIDTH:           

CARAPACE O.C. LENGTH:            CARAPACE O.C. WIDTH:           

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:           

TAG DATE:            TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C-0022  
VESSEL NAME: Starveant FIRM NAME: Brian Starveant  
LOAD NUMBER: 102 LOADING START TIME (24 HR): 0032 DATE: 4-28-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10 knots, Seas 2-4  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW: \_\_\_\_\_  
PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: Trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 1120 + 00 - 1160 + 00  
1720 3022 347N 88 01 290W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: ERIC Westergren  
OBSERVER'S SIGNATURE: Eric Westergren

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C-0022  
VESSEL NAME: Stacy's Sun FIRM NAME: BIGAL STACY'S  
LOAD NUMBER: 103 LOADING START TIME (24 HR): 0433 DATE: 4-28-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: GOOD  
WEATHER CONDITIONS: WINDS 10 knots, SEAS 2-4  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW:       

PORT SCREEN CONTENTS: Rock trash

STARBOARD SCREEN CONTENTS: trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120100-1160100

1120 30 22 923N 88 01 214W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:       

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES:        NO:       

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:       

HEAD WIDTH:        PLASTRON LENGTH:       

CARAPACE S.L. LENGTH:        CARAPACE S. L. WIDTH:       

CARAPACE O.C. LENGTH:        CARAPACE O.C. WIDTH:       

SPECIMEN CONDITION: ALIVE:        DEAD:        INJURED:        OTHER:       

TURTLE INITIALLY TAGGED? YES:        NO:        TAG NO:       

TAG DATE:        TURTLE RELEASED WITH TAG? YES:        NO:       

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stacyversant FIRM NAME: Becon Stacyversant  
LOAD NUMBER: 104 LOADING START TIME (24 HR): 0845 DATE: 9-28-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: \_\_\_\_\_  
WEATHER CONDITIONS: WIND 10-15 S-95 2-4  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW: \_\_\_\_\_  
PORT SCREEN CONTENTS: Trash

STARBOARD SCREEN CONTENTS: Trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES \_\_\_\_\_ NO ☒

COMMENTS AND OBSERVATIONS: 1120700 - 1080700  
1420 30 22 95 8N 88-01-216W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: ERIC Westerman

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_

PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_

CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_

CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: \_\_\_\_\_

DEAD: \_\_\_\_\_

INJURED: \_\_\_\_\_

OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Brian Stuyvesant  
LOAD NUMBER: 105 LOADING START TIME (24 HR): 1301 DATE: 4-28-09  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION:             
WEATHER CONDITIONS: WINDS 10-15 KAS SEA 2-4'  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW ☒ OVER-FLOW: ☐  
PORT SCREEN CONTENTS: TRASH

STARBOARD SCREEN CONTENTS: TRASH

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 1120+00-1080+00  
H2O 30° 23.76 N 88° 01.080 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:             
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: R. Kimberly Resor  
OBSERVER'S SIGNATURE: Kimberly Resor

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:             
HEAD WIDTH:            PLASTRON LENGTH:             
CARAPACE S.L. LENGTH:            CARAPACE S. L. WIDTH:             
CARAPACE O.C. LENGTH:            CARAPACE O.C. WIDTH:             
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:             
TAG DATE:            TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS:

## SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

COMMENTS AND OBSERVATIONS:



2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Beaumont Stuyvesant  
LOAD NUMBER: 107 LOADING START TIME (24 HR): 2126 DATE: 4-28-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO DEFLECTOR CONDITION:             
WEATHER CONDITIONS: NE WINDS 12-15 KTS 3-4'  
WATERWAY TEMP (°F): SURFACE: 75 MID-DEPTH TO WATER BOTTOM: 74

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW:           

PORT SCREEN CONTENTS:           

STARBOARD SCREEN CONTENTS:           

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES            NO ☒

COMMENTS AND OBSERVATIONS: 1120+00-1080+00

17.0 30°23.180N 88°01.128W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:           

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES:            NO:           

NAME OF SCREEN WATCH OBSERVER: Kimberly Peters

OBSERVER'S SIGNATURE: Kimberly Peters

DATA ON TURTLES RETAINED IN HOPPER

SPECIES:           

HEAD WIDTH:            PLASTRON LENGTH:           

CARAPACE S.L. LENGTH:            CARAPACE S. L. WIDTH:           

CARAPACE O.C. LENGTH:            CARAPACE O.C. WIDTH:           

SPECIMEN CONDITION: ALIVE:            DEAD:            INJURED:            OTHER:           

TURTLE INITIALLY TAGGED? YES:            NO:            TAG NO:           

TAG DATE:            TURTLE RELEASED WITH TAG? YES:            NO:           

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C-0022  
VESSEL NAME: Starvrsant FIRM NAME: Brian Starvrsant  
LOAD NUMBER: 108 LOADING START TIME (24 HR): 0209 DATE: 9-29-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 7 knots Seas 2-4  
WATERWAY TEMP (°F): SURFACE: 28 MID-DEPTH TO WATER BOTTOM: 77

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW: \_\_\_\_\_

PORT SCREEN CONTENTS: Clay, trash

STARBOARD SCREEN CONTENTS: Clay, trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES \_\_\_\_\_ NO ☒

COMMENTS AND OBSERVATIONS: 1120700-1080700  
1120302L 983N 88 01227L

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: ERIC WESTERMAN

OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Starve-sant FIRM NAME: Brian Starve-sant  
LOAD NUMBER: 109 LOADING START TIME (24 HR): 0615 DATE: 4-29-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION:             
WEATHER CONDITIONS: Winds 10 knots, seas 2-4  
WATERWAY TEMP (°F): SURFACE: 78 MID-DEPTH TO WATER BOTTOM: 77

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW:             
PORT SCREEN CONTENTS: clay, trash, rock

STARBOARD SCREEN CONTENTS: clay, trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 1120 FOU - 1080 FOU  
1120 30 23 602 N 8801 150 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:             
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC WESTERMAN  
OBSERVER'S SIGNATURE: Eric Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:             
HEAD WIDTH:            PLASTRON LENGTH:             
CARAPACE S.L. LENGTH:            CARAPACE S. L. WIDTH:             
CARAPACE O.C. LENGTH:            CARAPACE O.C. WIDTH:             
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:             
TAG DATE:            TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Beaumont Stuyvesant  
LOAD NUMBER: 110 LOADING START TIME (24 HR): 1023 DATE: 4-29-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION:             
WEATHER CONDITIONS: Windy 15 knots, seas 2-4  
WATERWAY TEMP (°F): SURFACE: 78 MID-DEPTH TO WATER BOTTOM: 77

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW:           

PORT SCREEN CONTENTS:             
TRASH, clay, rock

STARBOARD SCREEN CONTENTS:             
TRASH, clay, rock

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 1120+00-1080+00  
1720 30 22 912N 8801 193W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:             
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kim Peters  
OBSERVER'S SIGNATURE:           

DATA ON TURTLES RETAINED IN HOPPER:  
SPECIES:             
HEAD WIDTH:            PLASTRON LENGTH:             
CARAPACE S.L. LENGTH:            CARAPACE S. L. WIDTH:             
CARAPACE O.C. LENGTH:            CARAPACE O.C. WIDTH:             
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:             
TAG DATE:            TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Brian Stuyvesant  
LOAD NUMBER: 111 LOADING START TIME (24 HR): 1506 DATE: 4-29-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION:             
WEATHER CONDITIONS: WINDS 15 KTS SEA 2-4  
WATERWAY TEMP (°F): SURFACE: 78 MID-DEPTH TO WATER BOTTOM: 77

SCREEN WATCH:

SCREEN TYPE: IN-FLOW ☒ OVER-FLOW:           

PORT SCREEN CONTENTS: TRASH

STARBOARD SCREEN CONTENTS: TRASH

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES            NO ☒

COMMENTS AND OBSERVATIONS: 1120100-1080100  
H20 30° 22.473 N 88° 01.81 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:           

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES:            NO:           

NAME OF SCREEN WATCH OBSERVER: Kris Peters  
OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:             
HEAD WIDTH:            PLASTRON LENGTH:             
CARAPACE S.L. LENGTH:            CARAPACE S. L. WIDTH             
CARAPACE O.C. LENGTH:            CARAPACE O.C. WIDTH             
SPECIMEN CONDITION: ALIVE:            DEAD:            INJURED:            OTHER:           

TURTLE INITIALLY TAGGED? YES:            NO:            TAG NO:           

TAG DATE:            TURTLE RELEASED WITH TAG? YES:            NO:           

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Brian Stuyvesant  
LOAD NUMBER: 112 LOADING START TIME (24 HR): 1936 DATE: 4-29-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO DEFLECTOR CONDITION:             
WEATHER CONDITIONS: WIND 15 KTS RAIN SEA 2-4'  
WATERWAY TEMP (°F): SURFACE: 78 MID-DEPTH TO WATER BOTTOM: 77

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW:           

PORT SCREEN CONTENTS: TRASH

STARBOARD SCREEN CONTENTS: TRASH

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES            NO ☒

COMMENTS AND OBSERVATIONS: 120x00 - 1080x00  
H20 30 22.973N 88° 01.185W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:           

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES:            NO:           

NAME OF SCREEN WATCH OBSERVER: K. Pataro  
OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:             
HEAD WIDTH:            PLASTRON LENGTH:             
CARAPACE S.L. LENGTH:            CARAPACE S. L. WIDTH:             
CARAPACE O.C. LENGTH:            CARAPACE O.C. WIDTH:             
SPECIMEN CONDITION: ALIVE:            DEAD:            INJURED:            OTHER:           

TURTLE INITIALLY TAGGED? YES:            NO:            TAG NO:           

TAG DATE:            TURTLE RELEASED WITH TAG? YES:            NO:           

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Beaumont Stuyvesant  
LOAD NUMBER: 113 LOADING START TIME (24 HR): 0005 DATE: 4-30-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Windy 15 knots, seas 2-4  
WATERWAY TEMP (°F): SURFACE: 77 MID-DEPTH TO WATER BOTTOM: 76

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW: \_\_\_\_\_  
PORT SCREEN CONTENTS: clay, trash

STARBOARD SCREEN CONTENTS: clay, trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 1120+00 - TURTLE  
1120 30 23 132 8801 1022  
drag goes in for fuel

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: ERIK Westerman  
OBSERVER'S SIGNATURE: Erik Westerman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S. L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O. C. LENGTH: \_\_\_\_\_ CARAPACE O. C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Starvicsant FIRM NAME: Brian Starvicsant  
LOAD NUMBER: 114 LOADING START TIME (24 HR): 1901 DATE: 9-30-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION:  
WEATHER CONDITIONS: WINDS 8-10 KTS RAIN OVERCAST 5452-3  
WATERWAY TEMP (°F): SURFACE: 73 MID-DEPTH TO WATER BOTTOM: 72

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW: \_\_\_\_\_  
PORT SCREEN CONTENTS: TRASH

STARBOARD SCREEN CONTENTS: TRASH

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES \_\_\_\_\_ NO ☒

COMMENTS AND OBSERVATIONS: 1120700-1080700

H20 30' 23.621 N 88° 01.140 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: Kim Peters

OBSERVER'S SIGNATURE: Kim Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_

PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_

CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_

CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: \_\_\_\_\_

DEAD: \_\_\_\_\_

INJURED: \_\_\_\_\_

OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

01431-9 Revised by Amdt DACW01-03-B-0007-0001

CARAPACE O.C. LENGTH: \_\_\_\_\_

CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: \_\_\_\_\_

DEAD: \_\_\_\_\_

INJURED: \_\_\_\_\_

OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

01431-9 Revised by Amdt DACW01-03-B-0007-0001



2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Beacon Stuyvesant  
LOAD NUMBER: 116 LOADING START TIME (24 HR): 307 DATE: 5-1-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10 knots, Seas 2-4'  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW:             
PORT SCREEN CONTENTS: Clay, rock, wood, trash

STARBOARD SCREEN CONTENTS: Clay, wood, trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 1120100-1050700  
1120 30 22 156N 88 01 219 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:             
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ERIC H. STEGEMAN  
OBSERVER'S SIGNATURE: Eric H. Stegeman

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:             
HEAD WIDTH:            PLASTRON LENGTH:             
CARAPACE S. L. LENGTH:            CARAPACE S. L. WIDTH:             
CARAPACE O. C. LENGTH:            CARAPACE O. C. WIDTH:             
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:             
TAG DATE:            TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Beaumont Stuyvesant  
LOAD NUMBER: 117 LOADING START TIME (24 HR): 711 DATE: 5-7-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10 knots, seas 2-3  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW:       

PORT SCREEN CONTENTS: rock, wood, trash

STARBOARD SCREEN CONTENTS: rock, wood, trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120700-1080700  
#20 30 23. 196N 88° 01. 161 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:       

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Maria Lettwich

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:       

HEAD WIDTH:        PLASTRON LENGTH:       

CARAPACE S.L. LENGTH:        CARAPACE S. L. WIDTH:       

CARAPACE O.C. LENGTH:        CARAPACE O.C. WIDTH:       

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:       

TAG DATE:        TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Beaumont Stuyvesant  
LOAD NUMBER: 118 LOADING START TIME (24 HR): 1100 DATE: 05/01/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10 knots, seas 2-3'  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS:

TRASH, WOOD, Rock

STARBOARD SCREEN CONTENTS:

TRASH, WOOD, Rock

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1100 + 00 - 1080 + 00

H<sub>2</sub>O 30° 23.145' N 88° 01.221' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kim Peters

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_

PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_

CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_

CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐

DEAD: ☐

INJURED: ☐

OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Bcan Stuyvesant  
LOAD NUMBER: 119 LOADING START TIME (24 HR): 1546 DATE: 5.1.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO DEFLECTOR CONDITION: \_\_\_\_\_  
WEATHER CONDITIONS: WINDS 10/KNOTS SWS 2-3'  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW: \_\_\_\_\_

PORT SCREEN CONTENTS: TRASH, WOOD, ROCK

STARBOARD SCREEN CONTENTS: SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES \_\_\_\_\_ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00 - 1080+00  
H20 30° 23.203 N 88° 01.175 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: Jim Peters  
OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Beck Stuyvesant  
LOAD NUMBER: 120 LOADING START TIME (24 HR): 1958 DATE: 5.1.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION:             
WEATHER CONDITIONS: WINDS 10 KNOTS SEAS 2-3  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE. IN-FLOW: X OVER-FLOW:             
PORT SCREEN CONTENTS: WOOD, ROCK, TRASH

STARBOARD SCREEN CONTENTS: Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120 +00 -1080 +00  
H20 30° 23.207' N 88° 01.169' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:           

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kim Peters

OBSERVER'S SIGNATURE: Kim Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:             
HEAD WIDTH:            PLASTRON LENGTH:             
CARAPACE S.L. LENGTH:            CARAPACE S. L. WIDTH:             
CARAPACE O.C. LENGTH:            CARAPACE O.C. WIDTH:             
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:           

TAG DATE:            TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C 0022  
VESSEL NAME: StarVestant FIRM NAME: Brian StarVestant  
LOAD NUMBER: 121 LOADING START TIME (24 HR): 0010 DATE: 05/02/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Heavy Rain with lightning, winds 10 k sea 1-2'  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: mud, clay, wood, trash

STARBOARD SCREEN CONTENTS: mud, clay, wood, trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00 - 1050+00

1120 30° 23 20.7' N 88° 01 16.9' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ALICIA ALLETTWICK

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S.L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Beck Stuyvesant  
LOAD NUMBER: 122 LOADING START TIME (24 HR): 0414 DATE: 05/02/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: 6000  
WEATHER CONDITIONS: Winds 15 knts, sea 1-2'  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: wood, mud + clay

STARBOARD SCREEN CONTENTS: wood, mud + clay

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00 - 1050+00  
H2O 30° 23.040' N 88° 01.216' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Alicia L Leftwich

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C-0022  
VESSEL NAME: Steyversant FIRM NAME: Bican Steyversant  
LOAD NUMBER: 123 LOADING START TIME (24 HR): 0819 DATE: 5/2/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 15-20 knots, Aug 1-21  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: wood, trash, mud, clay

STARBOARD SCREEN CONTENTS: wood, trash, mud, clay

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1126+00 - 1080+00

H<sub>2</sub>O 30° 23.039'N 88° 01.207'W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ALICIA L LEPENICH

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_

PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_

CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_

CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐

DEAD: ☐

INJURED: ☐

OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_



2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Bcan Stuyvesant  
LOAD NUMBER: 124 LOADING START TIME (24 HR): 1223 DATE: 5/2/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION:             
WEATHER CONDITIONS: Wind 10 knots seas <1'  
WATERWAY TEMP (°F): SURFACE: 73 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: TRASH WOOD ROCK  
Southern Sting Ray - tossed

STARBOARD SCREEN CONTENTS: TRASH WOOD ROCK

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00 - 1080+00  
H20 30°23.029N 88°01.204W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:           

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kim Peters

OBSERVER'S SIGNATURE: Kim Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:             
HEAD WIDTH:            PLASTRON LENGTH:             
CARAPACE S.L. LENGTH:            CARAPACE S. L. WIDTH:             
CARAPACE O.C. LENGTH:            CARAPACE O.C. WIDTH:             
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:           

TAG DATE:            TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C-0022  
VESSEL NAME: Stevens FIRM NAME: Brian Stevens  
LOAD NUMBER: 125 LOADING START TIME (24 HR): 1641 DATE: 5-2-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO DEFLECTOR CONDITION: GOOD  
WEATHER CONDITIONS: WIND 10-15 KTS SEAS 2-3'  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS:

TRASH WOOD Net

STARBOARD SCREEN CONTENTS:

SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120 +00 - 160 +00

H20 30° 23.162N 88 01.161 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kim Peters

OBSERVER'S SIGNATURE: Kim Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: ☐

HEAD WIDTH: ☐

PLASTRON LENGTH: ☐

CARAPACE S.L. LENGTH: ☐

CARAPACE S. L. WIDTH: ☐

CARAPACE O.C. LENGTH: ☐

CARAPACE O.C. WIDTH: ☐

SPECIMEN CONDITION: ALIVE: ☐

DEAD: ☐

INJURED: ☐

OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐

NO: ☐

TAG NO: ☐

TAG DATE: ☐

TURTLE RELEASED WITH TAG? YES: ☐

NO: ☐

COMMENTS AND OBSERVATIONS: ☐

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Bican Stuyvesant  
LOAD NUMBER: 126 LOADING START TIME (24 HR): \_\_\_\_\_ DATE: 5-2-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO DEFLECTOR CONDITION: \_\_\_\_\_  
WEATHER CONDITIONS: WINDS 10-12 Kts clearing seas 2-3'  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW: \_\_\_\_\_

PORT SCREEN CONTENTS: \_\_\_\_\_

trash, wood, metal, plastic

STARBOARD SCREEN CONTENTS: \_\_\_\_\_

SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES \_\_\_\_\_ NO \_\_\_\_\_

COMMENTS AND OBSERVATIONS: 1120+00-1080+00  
H2O 30° 23. N 88° 01. W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: \_\_\_\_\_

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: \_\_\_\_\_

OBSERVER'S SIGNATURE: Kim Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Bcan Stuyvesant  
LOAD NUMBER: 127 LOADING START TIME (24 HR): 0041 DATE: 05/03/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10 knots, seas 1-2'  
WATERWAY TEMP (°F): SURFACE: 73 MID-DEPTH TO WATER BOTTOM: 72

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: wood, clay + mud

STARBOARD SCREEN CONTENTS: wood, clay, + mud

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120 + 00 - 1080 + 00  
H<sub>2</sub>O 30° 23, 195' N 88° 01, 216' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: No

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: AUCIA L LEFTWICH

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Bican Stuyvesant  
LOAD NUMBER: 128 LOADING START TIME (24 HR): 0450 DATE: 5/3/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10-15 knots, seas 1-2'  
WATERWAY TEMP (°F): SURFACE: 73 MID-DEPTH TO WATER BOTTOM: 72

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: wood, clay, mud, trash

STARBOARD SCREEN CONTENTS: wood, clay, mud, trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00 - 1080+00

H2O 30°23.140'N 88°06.165'W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ALICIA L LEFTWICH

OBSERVER'S SIGNATURE: Alicia L Leftwich

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Staryvesant FIRM NAME: Bcan Staryvesant  
LOAD NUMBER: 129 LOADING START TIME (24 HR): 0909 DATE: 5/3/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WIND 10 knots, seas < 1'  
WATERWAY TEMP (°F): SURFACE: 73 MID-DEPTH TO WATER BOTTOM: 72

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: wood, clay, trash

STARBOARD SCREEN CONTENTS: wood, clay, trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00 - 1080+00  
H<sub>2</sub>O 30°23.063 N 88°01.220 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: AUCIA K LEFTWICK

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Stavvessant FIRM NAME: Bear Stavvessant  
LOAD NUMBER: 130 LOADING START TIME (24 HR): 1315 DATE: 5-3-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS N 12-15 KTS 2-3  
WATERWAY TEMP (°F): SURFACE: 73 MID-DEPTH TO WATER BOTTOM: 72

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW: \_\_\_\_\_

PORT SCREEN CONTENTS: WOOD TRASH

STARBOARD SCREEN CONTENTS: SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES \_\_\_\_\_ NO ☒

COMMENTS AND OBSERVATIONS: 1120 + 00 - 1080 + 00  
H20 30° 23.180 N 88 01.213 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: Kim Peters  
OBSERVER'S SIGNATURE: Kim Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Bican Stuyvesant  
LOAD NUMBER: 731 LOADING START TIME (24 HR): 1719 DATE: 5.3.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS NE 12-15 KTS 2-3' SEAS  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS:

Blue Crab, TRASH, WOOD, metal, shells,

STARBOARD SCREEN CONTENTS:

5 AM

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120 + 00 - 1080 + 00  
120 30° 23.572N 88° 01.154 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER:

OBSERVER'S SIGNATURE: Kim Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_



2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C-0022  
VESSEL NAME: Starvesant FIRM NAME: Brian Starvesant  
LOAD NUMBER: 132 LOADING START TIME (24 HR): 2130 DATE: 5.3.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS 10-12 KTS SWS 2-3  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐  
PORT SCREEN CONTENTS: TRASH WOOD

STARBOARD SCREEN CONTENTS: SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 1120+00-1080+00  
H20 30°23.568 N 88°01.162 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kim Peters  
OBSERVER'S SIGNATURE: Kim Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C-0022  
VESSEL NAME: Steyversant FIRM NAME: Brian Steyversant  
LOAD NUMBER: 133 LOADING START TIME (24 HR): 0141 DATE: 05/04/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS 10-15 knots, seas 1-2'  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: wood, mud, clay, trash

STARBOARD SCREEN CONTENTS: wood, mud, clay, trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00 - 1080+00 - 1040+00  
420 30° 23.703' N 88° 01.105 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:                     

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Alicia L. Leftwich

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:                       
HEAD WIDTH:                      PLASTRON LENGTH:                       
CARAPACE S.L. LENGTH:                      CARAPACE S. L. WIDTH:                       
CARAPACE O.C. LENGTH:                      CARAPACE O.C. WIDTH:                       
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:                     

TAG DATE:                      TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: Steyversant FIRM NAME: Bcan Steyversant  
LOAD NUMBER: 134 LOADING START TIME (24 HR): 0619 DATE: 5/4/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10-15 knots, seas 1-2'  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: wood, clay, mud, trash

STARBOARD SCREEN CONTENTS: wood, clay, mud, trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00 - 1080+00 - 1040+00  
#0 30 -23.924 N 88°01.085 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: AUCIA L LEFTWICH

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_

PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_

CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_

CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐

DEAD: ☐

INJURED: ☐

OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Brian Stuyvesant  
LOAD NUMBER: 135 LOADING START TIME (24 HR): 1041 DATE: 5/4/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS 15-20 knots sea 1-2'  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: \_\_\_\_\_

STARBOARD SCREEN CONTENTS: \_\_\_\_\_

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120+00 - 1080+00 - 1040+00  
H<sub>2</sub>O 30° 23.744 N 88° 01.142 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kim Peters

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Beaumont Stuyvesant  
LOAD NUMBER: 136 LOADING START TIME (24 HR): 1501 DATE: 5.4.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS 15-20 KTS Seas 2-3  
WATERWAY TEMP (°F): SURFACE: 79 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW:       

PORT SCREEN CONTENTS: TRASH ROCK WOOD

STARBOARD SCREEN CONTENTS: SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120 +00 - 1080 +00 - 1040 +00  
1720 30° 23.80' N 88° 01.07' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:       

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: King Peters

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:       

HEAD WIDTH:        PLASTRON LENGTH:       

CARAPACE S. L. LENGTH:        CARAPACE S. L. WIDTH:       

CARAPACE O. C. LENGTH:        CARAPACE O. C. WIDTH:       

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:       

TAG DATE:        TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Beck Stuyvesant  
LOAD NUMBER: 137 LOADING START TIME (24 HR): 1927 DATE: 5-4-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☒ DEFLECTOR CONDITION: ✓  
WEATHER CONDITIONS: WINDS 12-15 KTS SWAS 2-3'  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW:       

PORT SCREEN CONTENTS:

TRASH wood rock shell  
Blue CRAB

STARBOARD SCREEN CONTENTS:

SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: H20+00-1080+00-1040+00  
H20 30° 23.751 N 88° 01.192 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:       

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kim Peters

OBSERVER'S SIGNATURE: Kim Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:       

HEAD WIDTH:        PLASTRON LENGTH:       

CARAPACE S.L. LENGTH:        CARAPACE S. L. WIDTH:       

CARAPACE O.C. LENGTH:        CARAPACE O.C. WIDTH:       

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:       

TAG DATE:        TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Starvesant FIRM NAME: Beck Starvesant  
LOAD NUMBER: 138 LOADING START TIME (24 HR): 0000 DATE: 5/5/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS 12-15, seas 2-3'  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: trash, wood, clay, mud

STARBOARD SCREEN CONTENTS: trash, wood, clay, mud

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: H20 + 00 - 100 H20 + 00 - 1080 + 00 - 1040 + 00  
1120' 30° 23' 750' N 88° 01' 152' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ALICIA L LEFTWICH

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S.L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: 0191275  
VESSEL NAME: St. Vincent FIRM NAME: Brown Street  
LOAD NUMBER: 39 LOADING START TIME (24 HR): 0412 DATE: 5/5/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 11 knots Seas < 1'  
WATERWAY TEMP (°F): SURFACE: 94 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: wood, trash, mud, clay

STARBOARD SCREEN CONTENTS: wood, trash, mud, clay

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 1120 + 00 1080 + 00 - 1040 + 00  
300 23. 751' N 88° 01. 152' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Alicia L Leftwich  
OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_



2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT Mobile Channel CONTRACT NO: W91278 04 C-0022  
VESSEL NAME: ST. JAMES FIRM NAME: BIGAN ST. JAMES  
LOAD NUMBER: 140 LOADING START TIME (24 HR): 0831 DATE: 5/15/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS 10 knots, seas < 1'  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH.

SCREEN TYPE. IN-FLOW ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: wood, clay, mud, trash

STARBOARD SCREEN CONTENTS: wood, clay, mud, trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 420+00 - 1080+00 - 1040+00  
140 30°23.684'N 88°01.109'W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:                       
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: N/D  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: AUCIA L LEFTWICH  
OBSERVER'S SIGNATURE: Aucia L Leftwich

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:                       
HEAD WIDTH:                      PLASTRON LENGTH:                       
CARAPACE S.L. LENGTH:                      CARAPACE S. L. WIDTH                       
CARAPACE O.C. LENGTH:                      CARAPACE O.C. WIDTH                       
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:                       
TAG DATE:                      TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT Mobile Channel CONTRACT NO: W91278-04-C-0022  
VESSEL NAME: ST. AUGUSTINE FIRM NAME: Brown Shipbuilding  
LOAD NUMBER: 141 LOADING START TIME (24 HR): 1249 DATE: 5/5/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Variable WINDS 5-8 KTS SEAS 4-2  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS:

TRASH & MUD

STARBOARD SCREEN CONTENTS:

SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1120-100-100-100 = 1040-100  
H2O 30° 23.962N 88° 01.054W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:                     

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: N/D

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Kim Poles

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES:                     

HEAD WIDTH:                      PLASTRON LENGTH:                     

CARAPACE S.L. LENGTH:                      CARAPACE S. L. WIDTH:                     

CARAPACE O.C. LENGTH:                      CARAPACE O.C. WIDTH:                     

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:                     

TAG DATE:                      TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91275 0-0-002-  
VESSEL NAME: Starboard FIRM NAME: Brown Starboard  
LOAD NUMBER: 142 LOADING START TIME (24 HR): 1721 DATE: 5.5.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: GOOD  
WEATHER CONDITIONS: Variable 5-8/65 seas < 2  
WATERWAY TEMP (°F). SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE. IN-FLOW X OVER-FLOW: \_\_\_\_\_

PORT SCREEN CONTENTS: \_\_\_\_\_

TRASH mud wood clam  
shell + blue crab

STARBOARD SCREEN CONTENTS: \_\_\_\_\_

SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: H20 +00-1080+00+1040+00  
H20 30° 23.95' N 88° 01.055 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: \_\_\_\_\_

OBSERVER'S SIGNATURE: \_\_\_\_\_

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_

PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_

CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_

CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: \_\_\_\_\_

DEAD: \_\_\_\_\_

INJURED: \_\_\_\_\_

OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_

TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C-0022  
VESSEL NAME: St. Vincent FIRM NAME: Beaumont  
LOAD NUMBER: 143 LOADING START TIME (24 HR): 2118 DATE: 5.5.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS NE 8-10 KTS SWS 42  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH

SCREEN TYPE IN-FLOW ☒ OVER-FLOW: \_\_\_\_\_  
PORT SCREEN CONTENTS: \_\_\_\_\_

STARBOARD SCREEN CONTENTS: \_\_\_\_\_

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES \_\_\_\_\_ NO ☒  
COMMENTS AND OBSERVATIONS: 1120 to 1080 + 00 - 1040 + 00  
1120 30°23.901N 88°01.051W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: Kim Peters

OBSERVER'S SIGNATURE: Kim Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C 0022  
VESSEL NAME: Starvesant FIRM NAME: Brian Starvesant  
LOAD NUMBER: 144 LOADING START TIME (24 HR): 0134 DATE: 5/6/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS 5-7 knots, seas < 1'  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐  
PORT SCREEN CONTENTS: wood, trash, mud, cgy

STARBOARD SCREEN CONTENTS: wood, trash, mud, cgy

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 1120+00 - 1080+00 - 1040+00  
1130 30° 23.90' N 88° 01.05' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ALICIA L. LEFTWICH  
OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C 0022  
VESSEL NAME: Starversant FIRM NAME: Brian Starversant  
LOAD NUMBER: 145 LOADING START TIME (24 HR): 0540 DATE: 5/6/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Variable wind @ 5-10 knots, Alon calm  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: wood, trash, rock, mud, clay

STARBOARD SCREEN CONTENTS: wood, trash, rock, mud, clay

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 1120 + 00 - 1080 + 00 - 1040 + 00  
1120 30° 23.678'N 88° 01.109'W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ALICIA L LEFTWICH

OBSERVER'S SIGNATURE: Alicia L Leftwich

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Bican Stuyvesant  
LOAD NUMBER: 146 LOADING START TIME (24 HR): 1008 DATE: 5/6/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: \_\_\_\_\_  
WEATHER CONDITIONS: light winds, calm seas  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: \_\_\_\_\_

PORT SCREEN CONTENTS: WOOD, TRASH, ROCK, MUD  
FRISBEES

STARBOARD SCREEN CONTENTS: \_\_\_\_\_  
SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES \_\_\_\_\_ NO ☒

COMMENTS AND OBSERVATIONS: 1030+00 - 1040+00  
20 30°23.867'N 88°01.071'W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: Kim Peters

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C 0022  
VESSEL NAME: Starbuck FIRM NAME: Brown Starbuck  
LOAD NUMBER: 147 LOADING START TIME (24 HR): 1421 DATE: 5.6.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS S 5-8 KTS SEAS < 2 80°F  
WATERWAY TEMP (°F): SURFACE: 75 MID-DEPTH TO WATER BOTTOM: 74

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: TRASH ROCK CLAY

STARBOARD SCREEN CONTENTS: SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 1080 +00 - 1040 +00  
1700 30°23.748 N 88° 01.084 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: Kim Peters  
OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_



2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C 0022  
VESSEL NAME: Starve-sant FIRM NAME: Bear Starve-sant  
LOAD NUMBER: 188 LOADING START TIME (24 HR): 1846 DATE: 5.6.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS 8 58 KTS SWS 2  
WATERWAY TEMP (°F): SURFACE: 75 MID-DEPTH TO WATER BOTTOM: 74

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: X OVER-FLOW: \_\_\_\_\_

PORT SCREEN CONTENTS:

TRASH WOOD MUD ROCK

STARBOARD SCREEN CONTENTS: SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES \_\_\_\_\_ NO ☒

COMMENTS AND OBSERVATIONS: 1080 + 00 - 1040 + 00  
H2O 30° 23.930 N 88° 01.100 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES: \_\_\_\_\_ NO: \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: Kim Peters

OBSERVER'S SIGNATURE: Kim Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-04 C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Beck Stuyvesant  
LOAD NUMBER: 149 LOADING START TIME (24 HR): 2311 DATE: 5-6-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS 5-10 KTS SEAS 12  
WATERWAY TEMP (°F): SURFACE: 75 MID-DEPTH TO WATER BOTTOM: 74

SCREEN WATCH:

SCREEN TYPE: IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: wood, rock, mud, clay

STARBOARD SCREEN CONTENTS: wood, rock, mud, clay

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1080+00-1040+00  
H2O 30° 23.787N 88° 01.073W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: Alicia L Leftwich

OBSERVER'S SIGNATURE: Alicia L Leftwich

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C 0022  
VESSEL NAME: Stacy's FIRM NAME: Beach Stacy's  
LOAD NUMBER: 150 LOADING START TIME (24 HR): 0313 DATE: 5/7/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: good  
WEATHER CONDITIONS: calm winds + seas  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE. IN-FLOW ☒ OVER-FLOW: ☐  
PORT SCREEN CONTENTS: wood, rock, trash, mud + clay

STARBOARD SCREEN CONTENTS: wood, rock, trash, mud + clay

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1080 + 00 - 1040 + 00  
30° 23.786' N 88° 01.074' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ALICIA L LEFTWICH

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278 04 C 0022  
VESSEL NAME: Stumpert FIRM NAME: Bear Stevedoring  
LOAD NUMBER: 151 LOADING START TIME (24 HR): 0745 DATE: 5/7/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds variable @ 5 knots, sea calm  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH:

SCREEN TYPE: IN-FLOW ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: wood, trash, mud, clay

STARBOARD SCREEN CONTENTS: wood, trash, mud, clay

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1080±00 - 1040±00

H<sub>2</sub>O 30°23, 726 'N 88° 01 132'W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES: ☐ NO: ☐

NAME OF SCREEN WATCH OBSERVER: ALICIA L LEFTWICH

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT Mobile Channel CONTRACT NO. W9127804 C-0022  
VESSEL NAME Stuyvesant FIRM NAME Bear Stuyvesant  
LOAD NUMBER 152 LOADING START TIME (24 HR): 1205 DATE 5.7.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION Good  
WEATHER CONDITIONS Winds variable 5 kts Seas calm  
WATERWAY TEMP (°F) SURFACE 75 MID-DEPTH TO WATER BOTTOM 74

SCREEN WATCH

SCREEN TYPE IN-FLOW ☒ OVER-FLOW ☐

PORT SCREEN CONTENTS TRASH MUD ROCK shell  
Shackel wood

STARBOARD SCREEN CONTENTS

SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS 1080+00-1040+00  
120 30°23.869 N 88°01.079 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER:

OBSERVER'S SIGNATURE Kim Peter

DATA ON TURTLES RETAINED IN HOPPER

SPECIES

HEAD WIDTH: PLASTRON LENGTH:

CARAPACE S.L. LENGTH: CARAPACE S.L. WIDTH:

CARAPACE O.C. LENGTH: CARAPACE O.C. WIDTH:

SPECIMEN CONDITION: ALIVE: DEAD: INJURED: OTHER:

TURTLE INITIALLY TAGGED? YES: NO: TAG NO:

TAG DATE TURTLE RELEASED WITH TAG? YES: NO:

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT Mobile Channel CONTRACT NO. W9127804-C0022  
VESSEL NAME Stuyvesant FIRM NAME Bear Stuyvesant  
LOAD NUMBER 153 LOADING START TIME (24 HR) 1628 DATE 5.7.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION Good  
WEATHER CONDITIONS WIND S South 10 Kts SEAS 2  
WATERWAY TEMP (°F) SURFACE 76 MID-DEPTH TO WATER BOTTOM 75

SCREEN WATCH

SCREEN TYPE IN-FLOW ☒ OVER-FLOW ☐

PORT SCREEN CONTENTS

TRASH WOOD MUD

STARBOARD SCREEN CONTENTS

SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS 1080+00-1090+00  
#20 30°23.8'N 88°01.08'W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: Kim Peters

OBSERVER'S SIGNATURE: Kim Peters

DATA ON TURTLES RETAINED IN HOPPER

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Bea Stuyvesant  
LOAD NUMBER: 154 LOADING START TIME (24 HR): 2050 DATE: 5.7.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: KINDS 5-10 KTS  
WATERWAY TEMP (°F): SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH

SCREEN TYPE: IN-FLOW ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS

TRASH WOOD PLASTIC metal

STARBOARD SCREEN CONTENTS:

SAMP

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1080 + 00 - 1040 + 00

H20 30°23.785N 88°01.072W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: Kim Peters

OBSERVER'S SIGNATURE: Kim Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_

PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_

CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_

CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: \_\_\_\_\_

DEAD: \_\_\_\_\_

INJURED: \_\_\_\_\_

OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME Stuyvesant FIRM NAME: Bean Stuyvesant  
LOAD NUMBER 155 LOADING START TIME (24 HR): 0113 DATE: 5/8/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WINDS 5-10 knots, seas calm  
WATERWAY TEMP (°F) SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH

SCREEN TYPE IN-FLOW ☒ OVER-FLOW: ☐  
PORT SCREEN CONTENTS wood, rock, mud, clay, trash

STARBOARD SCREEN CONTENTS: wood, rock, mud, clay, trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1080' to 1040' to

30' 23.726' 1180' to 132' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: ALICIA I LEPTWICK

OBSERVER'S SIGNATURE: Alicia I Leptwick

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES \_\_\_\_\_  
HEAD WIDTH \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_



2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME STUYVESANT FIRM NAME: Beaumont Stuyvesant  
LOAD NUMBER 156 LOADING START TIME (24 HR): 0520 DATE: 5/8/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: calm winds + seas  
WATERWAY TEMP (°F): SURFACE: 74 MID-DEPTH TO WATER BOTTOM: 73

SCREEN WATCH

SCREEN TYPE: IN-FLOW ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS: mud, clay, weed, trash, rock

STARBOARD SCREEN CONTENTS: mud, clay, weed, trash, rock

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1080+00 - 1040 700  
30° 23.726' N 88° 01.132' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: ALICIA L LEFTWICH

OBSERVER'S SIGNATURE: Alicia L Leftwich

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME STUYVESANT FIRM NAME Bean Stuyvesant  
LOAD NUMBER 157 LOADING START TIME (24 HR): 0943 DATE 5/8/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION Good  
WEATHER CONDITIONS calm windy & sunny  
WATERWAY TEMP (°F) SURFACE 76 MID-DEPTH TO WATER BOTTOM 75

SCREEN WATCH

SCREEN TYPE IN-FLOW ☒ OVER-FLOW ☐

SCREEN CONTENTS TRASH MUD WOOD ROCK

BEHIND SCREEN CONTENTS SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COORDINATES AND OBSERVATIONS. 1080400-1040+00  
30°23.726' N 88°01.132' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBORD DRAGHEAD: No

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER Kim Peters

OBSERVER'S SIGNATURE Kim Peters

DATA ON TURTLES RETAINED IN HOPPER

SEXES \_\_\_\_\_

HEAD WIDTH \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH \_\_\_\_\_

SPECIMEN CONDITION ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

## SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

## SCIENCE WATCH

SCREEN TYPE IN-FLOW ~~X~~ OVER-FLOW:

ARTICLES, CONTENTS

MUD TRASH ROCK WOOD

## STANDARD SCREEN CONTENTS

same

DO FILE OR TURTLE PARTS PRESENT THIS LOAD?: YES NO ☒

COMMENTS AND OBSERVATIONS: 108 of 00 - 104 of 00

$120^{\circ} 30' 23.674'' \text{N}$   $88^{\circ} 01.144'' \text{W}$

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:

FUR TLE PARTS PRESENT IN PORT OR STARBORD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES NO

NAME OF SCREEN WATCH OBSERVER: *[Signature]*

SERVER'S SIGNATURE \_\_\_\_\_

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES

HEAD WIDTH PLASTRON LENGTH:

CARAPACE S. L. LENGTH: CARAPACE S. L. WIDTH:

CARAPACE O.C. LENGTH CARAPACE O.C. WIDTH

SPECIMEN CONDITION: ALIVE: DEAD: INJURED: OTHER:

TURTLE INITIALLY TAGGED? YES: NO: TAG NO:

TAG DATE \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME Stuyvesant FIRM NAME: Bean Stuyvesant  
LOAD NUMBER 159 LOADING START TIME (24 HR): 1835 DATE: 5-8-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS WINDS 5-10 KTS SEAS < 2'  
WATERWAY TEMP (°F) SURFACE: 77 MID-DEPTH TO WATER BOTTOM: 76

SCREEN WATCH

SCREEN TYPE IN-FLOW ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS

lots of extra clay covering the wood,  
plastic, metal, + net stuff

STARBOARD SCREEN CONTENTS

SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1080 + 00 - 1040 + 00  
42° 30' 23.669 N 88° 01' 138 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:                     

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: Kim Peters

OBSERVER'S SIGNATURE: Kim Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES                     

HEAD WIDTH                      PLASTRON LENGTH:                     

CARAPACE S.L. LENGTH:                      CARAPACE S. L. WIDTH                     

CARAPACE O.C. LENGTH:                      CARAPACE O.C. WIDTH                     

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:                     

TAG DATE                      TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT Mobile Channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Bean Stuyvesant  
LOAD NUMBER 160 LOADING START TIME (24 HR): 2350 DATE: \_\_\_\_\_  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION Good  
WEATHER CONDITIONS WINDS 5-10/GS SW - 2-3'  
WATERWAY TEMP (°F) SURFACE 76 MID-DEPTH TO WATER BOTTOM 75

SCREEN WATCH

SCREEN TYPE IN-FLOW ☒ OVER-FLOW \_\_\_\_\_  
PORT SCREEN CONTENTS \_\_\_\_\_

STARBOARD SCREEN CONTENTS \_\_\_\_\_

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES \_\_\_\_\_ NO \_\_\_\_\_

COMMENTS AND OBSERVATIONS. 1080 +00 - 1040 +00

H2O 30° 24' 12" N 88° 01.035 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: \_\_\_\_\_

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES \_\_\_\_\_ NO \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: \_\_\_\_\_

OBSERVER'S SIGNATURE \_\_\_\_\_

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES \_\_\_\_\_

HEAD WIDTH \_\_\_\_\_

PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_

CARAPACE S. L. WIDTH \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_

CARAPACE O.C. WIDTH \_\_\_\_\_

SPECIMEN CONDITION ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT Mobile Channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME Stuyvesant FIRM NAME: Beaumont Stuyvesant  
LOAD NUMBER 160 LOADING START TIME (24 HR): 2350 DATE: 5/9/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS WINDS 5-10 KTS SW - 23'  
WATERWAY TEMP (°F) SURFACE: 76 MID-DEPTH TO WATER BOTTOM 75

SCREEN WATCH

SCREEN TYPE IN-FLOW ☒ OVER-FLOW ☐

SCREEN CONTENTS wood, rocks, clay, mud

STARBOARD SCREEN CONTENTS wood, rocks, clay, mud

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1080+00 - 1040+00  
HWD 30° 24' 12" N 88° 01' 03.5" W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: ALYCIA L LEE TWK

OBSERVER'S SIGNATURE Alicia L Lee

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES \_\_\_\_\_

HEAD WIDTH \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH \_\_\_\_\_

CARAPACE O.C. LENGTH \_\_\_\_\_ CARAPACE O.C. WIDTH \_\_\_\_\_

SPECIMEN CONDITION ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME Stuyvesant FIRM NAME: Bea Stuyvesant  
LOAD NUMBER 161 LOADING START TIME (24 HR): 0311 DATE: 5/19/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 5-10, seas 1-2'  
WATERWAY TEMP (°F) SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH

SCREEN TYPE IN-FLOW: ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS wood, rock, trash, mud, clay

STARBOARD SCREEN CONTENTS wood, rock, trash, mud, clay

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1080 to 0 - 1040 to 0

30° 24.112' N 88° 01.035' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: ALICIA LUTNICK

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_

PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_

CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_

CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME STUYVESANT FIRM NAME: Bean STUYVESANT  
LOAD NUMBER 162 LOADING START TIME (24 HR): 0735 DATE: 5/9/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Windy 10-15, Seas 2-3'  
WATERWAY TEMP (°F). SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH

SCREEN TYPE IN-FLOW ☒ OVER-FLOW: ☐  
PORT SCREEN CONTENTS clay, weed, trash

STARBOARD SCREEN CONTENTS: clay, weed, trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1080+00-1080+00  
30° 23.672' N 88° 01.112' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: No

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: ALICIA L LEPTWICHT

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES \_\_\_\_\_

HEAD WIDTH \_\_\_\_\_

PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_

CARAPACE S. L. WIDTH \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_

CARAPACE O.C. WIDTH \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐

DEAD: ☐

INJURED: ☐

OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE \_\_\_\_\_

TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_



2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT Mobile Channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: Bea Stuyvesant  
LOAD NUMBER: 145 LOADING START TIME (24 HR): 1237 DATE: 5/19/01  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: WIND 510-72 KTS SEAS 4-2  
WATERWAY TEMP (°F). SURFACE: 77 MID-DEPTH TO WATER BOTTOM: 76

SCREEN WATCH

SCREEN TYPE, IN-FLOW ☒ OVER-FLOW: ☐

PORT SCREEN CONTENTS

Large Amounts of Clay + mud, wood, rock

STARBOARD SCREEN CONTENTS

Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1080000-1040000  
H20 30° 24.00' N 88° 01.10' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:                     

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: Kim Posner

OBSERVER'S SIGNATURE: Kim Posner

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES                     

HEAD WIDTH:                     

PLASTRON LENGTH:                     

CARAPACE S.L. LENGTH:                     

CARAPACE S. L. WIDTH:                     

CARAPACE O.C. LENGTH:                     

CARAPACE O.C. WIDTH:                     

SPECIMEN CONDITION: ALIVE: ☐

DEAD: ☐

INJURED: ☐

OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:                     

TAG DATE                     

TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME Stuyvesant FIRM NAME: Bean Stuyvesant  
LOAD NUMBER 164 LOADING START TIME (24 HR): 1704 DATE: 5.9.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS WINDS 10-15 Kts SEAS 2-3'  
WATERWAY TEMP (°F) SURFACE: 77 MID-DEPTH TO WATER BOTTOM: 76

SCREEN WATCH

SCREEN TYPE IN-FLOW ☒ OVER-FLOW: ☐

SCREEN CONTENTS

Lots of mud & clay, wood, rock

STARBOARD SCREEN CONTENTS SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COORDINATES AND OBSERVATIONS: 1080+00 -1040+00  
Pro 30° 23.960 N 88° 04.046 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: Kim Peters

OBSERVER'S SIGNATURE: Kim Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME Stuyvesant FIRM NAME Beaumont Stuyvesant  
LOAD NUMBER 105 LOADING START TIME (24 HR): 2121 DATE 5-9-04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION Good  
WEATHER CONDITIONS WINDS 10-15 KTS SEAS 2-3'  
WATERWAY TEMP (°F) SURFACE 77 MID-DEPTH TO WATER BOTTOM 76

SCREEN WATCH

SCREEN TYPE IN-FLOW ☒ OVER-FLOW ☐

SCREEN CONTENTS MUD & CLAY  
WOOD plastic metal

BEHIND SCREEN CONTENTS \_\_\_\_\_

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COORDINATES AND OBSERVATIONS 1080 + 00 - 1040 + 00  
H20 30° 23.752N 88° 01.094W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER Kim Peters

OBSERVER'S SIGNATURE Kim Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES \_\_\_\_\_

HEAD WIDTH \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S. L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH \_\_\_\_\_

CARAPACE O. C. LENGTH: \_\_\_\_\_ CARAPACE O. C. WIDTH \_\_\_\_\_

EXHIBIT CONDITION ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES ☐ NO ☐ TAG NO: \_\_\_\_\_

RELEASE DATE \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES ☐ NO ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO. W9127804-C-0022  
VESSEL NAME Stuyvesant FIRM NAME Bea Stuyvesant  
LOAD NUMBER 166 LOADING START TIME (24 HR): 0138 DATE: 5/10/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION Good  
WATER CONDITIONS Winds 5-10 knots, Seas 2-3'  
WATERWAY TEMP (°F) SURFACE: 76 MID-DEPTH TO WATER BOTTOM 75

SCREEN WATCH  
LOAD TYPE IN-FLOW ☒ OVER-FLOW ☐  
SCREEN CONTENTS wood, clay, mud, trash

DRAGHEAD SCREEN CONTENTS wood, clay, mud, trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS. 1080+00 - 1040+00  
30° 23' 752' N 88° 01' 094' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER ALICIA L. LEPTWICH  
OBSERVER'S SIGNATURE [Signature]

WAS ANY TURTLES RETAINED IN HOPPER  
YES ☐ NO ☐

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S. L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O. C. LENGTH: \_\_\_\_\_ CARAPACE O. C. WIDTH: \_\_\_\_\_  
TURTLE CONDITION ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

"TURTLE INITIALLY TAGGED" YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME Stuyvesant FIRM NAME: Bean Stuyvesant  
LOAD NUMBER 167 LOADING START TIME (24 HR): 0554 DATE: 5/10/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS WINDS 10-15, Seas < 1'  
WATERWAY TEMP (°F) SURFACE: 76 MID-DEPTH TO WATER BOTTOM: 75

SCREEN WATCH

SCREEN TYPE IN-FLOW ☒ OVER-FLOW: ☐  
SCREENED CONTENTS wood, mud, clog, trash, rock

STARBOARD SCREEN CONTENTS wood, mud, clog, trash, rock

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COORDINATES AND OBSERVATIONS. 1080 100 - 1040 100  
300 23.705'N 88° 06.117'W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: ALICIA L LEFTWICH

OBSERVER'S SIGNATURE: *Alicia L Leftwich*

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES \_\_\_\_\_

HEAD WIDTH \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S. L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH \_\_\_\_\_

CARAPACE O. C. LENGTH: \_\_\_\_\_ CARAPACE O. C. WIDTH \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.3 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO. W9127804-C-0022  
VESSEL NAME STUYVESANT FIRM NAME Bean Stuyvesant  
LOAD NUMBER 168 LOADING START TIME (24 HR): 1008 DATE 5/10/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION Good  
WEATHER CONDITIONS WINDS 10-15, from E  
WATERWAY TEMP (°F) SURFACE 76 MID-DEPTH TO WATER BOTTOM 75

SCREEN WATCH

SCREEN TYPE IN-FLOW ☒ OVER-FLOW ☐

SCREEN CONTENTS

Clay MUD WOOD FRAGILE ROCK

DRAGHEAD SCREEN CONTENTS

STONE

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COORDINATES AND OBSERVATIONS 1080+00 - 1040+00  
30° 23.755 'N 88° 01.093 'W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: \_\_\_\_\_

OBSERVER'S SIGNATURE Kim Peters

NUMBER OF TURTLES RETAINED IN HOPPER

SPECIES \_\_\_\_\_

HEAD WIDTH \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S. L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH \_\_\_\_\_

CARAPACE O. C. LENGTH: \_\_\_\_\_ CARAPACE O. C. WIDTH \_\_\_\_\_

PLASTRON CONDITION ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES ☐ NO ☐ TAG NO: \_\_\_\_\_

DATE \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES ☐ NO ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME Stuyvesant FIRM NAME Bean Stuyvesant  
LOAD NUMBER 169 LOADING START TIME (24 HR): 1437 DATE 5.10.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION Good  
WEATHER CONDITIONS WINDS 15 + KTS SEAS 2-4  
WATERWAY TEMP (°F) SURFACE 78 MID-DEPTH TO WATER BOTTOM 77

SCREEN WATCH  
SCREEN TYPE IN-FLOW ☒ OVER-FLOW ☐  
SCREEN CONTENTS TRASH & mud

DRAGHEAD AND SCREEN CONTENTS SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS 100-1000 NEW station  
H20 30°24.849 88°00.928

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBORD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER Kim Peters  
OBSERVER'S SIGNATURE [Signature]

DATA ON TURTLES RETAINED IN HOPPER  
SPECIES \_\_\_\_\_  
HEAD WIDTH \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S. L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH \_\_\_\_\_  
CARAPACE O. C. LENGTH: \_\_\_\_\_ CARAPACE O. C. WIDTH \_\_\_\_\_  
HEALTH CONDITION ALIVE ☐ DEAD ☐ INJURED ☐ OTHER ☐

TURTLE INITIALLY TAGGED? YES ☐ NO ☐ TAG NO: \_\_\_\_\_  
TAG DATE \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES ☐ NO ☐  
COMMENTS AND OBSERVATIONS \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME Stuyvesant FIRM NAME: Bean Stuyvesant  
LOAD NUMBER 170 LOADING START TIME (24 HR): 1901 DATE: 5/0/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS WINDS 15 KTS SW 2-4  
WATERWAY TEMP (°F) SURFACE: 77 MID-DEPTH TO WATER BOTTOM: 76

SCREEN WATCH

SCREEN TYPE IN-FLOW ☒ OVER-FLOW: ☐  
SCREEN CONTENTS TRASH MUD clay

STARBOARD SCREEN CONTENTS: SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒  
COMMENTS AND OBSERVATIONS: 1040-1000 STAT G  
H20 30°24.847 N 88°00.935 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: Kim Packer  
OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES \_\_\_\_\_  
HEAD WIDTH \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH \_\_\_\_\_  
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_  
TAG DATE \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_



2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO. W9127804-C-0022  
VESSEL NAME Stuyvesant FIRM NAME Bean Stuyvesant  
LOAD NUMBER 171 LOADING START TIME (24 HR): 2326 DATE 5/11/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION Good  
WEATHER CONDITIONS WINDS 10-15 knts, Seas 1-2'  
WATERWAY TEMP (°F) SURFACE 76 MID-DEPTH TO WATER BOTTOM 75

SCREEN WATCH  
SCREEN TYPE IN-FLOW ☒ OVER-FLOW ☐  
BEFORE SCREEN CONTENTS wood, clay, trash

AFTER AND SCREEN CONTENTS wood, clay, trash

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒  
COORDINATES AND OBSERVATIONS 1040+00 - 1000+00  
30° 24.847' N 88° 00.935' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER ALICIA L. LEFTWICH  
OBSERVER'S SIGNATURE *Alicia L. Leftwich*

DATA ON TURTLES RETAINED IN HOPPER

SPECIES \_\_\_\_\_  
HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_  
CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_  
SPECIMEN CONDITION ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

"TURTLE INITIALLY TAGGED" YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_  
TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO. W9127804-C-0022  
VESSEL NAME STUYVESANT FIRM NAME Bean STUYVESANT  
LOAD NUMBER 172 LOADING START TIME (24 HR): 0423 DATE 5/11/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION Good  
WEATHER CONDITIONS WINDS 10-15 knts. Seas 1-2'  
WATERWAY TEMP (°F) SURFACE 76 MID-DEPTH TO WATER BOTTOM 75

SCREEN WATCH  
SCREEN TYPE IN-FLOW ☒ OVER-FLOW ☐  
BEFORE SCREEN CONTENTS Wood, trash, clay

AFTER AND SCREEN CONTENTS Wood, trash, clay

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒  
DIMENSIONS AND OBSERVATIONS. 10'10" +00 - 1000' +00  
30" x 24" 847'10" 850'00 935'14

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_  
TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: No  
WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN? YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER ALICIA L. LEF7WICOT  
OBSERVER'S SIGNATURE [Signature]

DATA ON TURTLES RETAINED IN HOPPER  
SPECIES \_\_\_\_\_  
HEAD WIDTH \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_  
CARAPACE S. L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH \_\_\_\_\_  
CARAPACE O. C. LENGTH: \_\_\_\_\_ CARAPACE O. C. WIDTH \_\_\_\_\_  
PHYSICAL CONDITION ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_  
TAG DATE \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐  
COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME Stuyvesant FIRM NAME: Bean Stuyvesant  
LOAD NUMBER 173 LOADING START TIME (24 HR): 0905 DATE: 5/11/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS WINDS 10-15, Seas 1-2'  
WATERWAY TEMP (°F) SURFACE: 78 MID-DEPTH TO WATER BOTTOM: 77

SCREEN WATCH

SCREEN TYPE IN-FLOW ☒ OVER-FLOW:                       
PORTER REEL CONTENTS rock, wood, trash, clay

STARBOARD SCREEN CONTENTS: rock, wood, trash, clay

TURTLE OR TURTLE PARTS PRESENT THIS LOAD?: YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1040 hrs - 1000+00  
30° 24.400' N 88° 01.016' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE:                     

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: ALICIA L. LEFTWICH  
OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES                       
HEAD WIDTH                      PLASTRON LENGTH:                       
CARAPACE S.L. LENGTH:                      CARAPACE S. L. WIDTH                       
CARAPACE O.C. LENGTH:                      CARAPACE O.C. WIDTH                       
SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO:                     

TAG DATE                      TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS:

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME STUYVESANT FIRM NAME Bea STUYVESANT  
LOAD NUMBER 174 LOADING START TIME (24 HR): 1327 DATE: 5.11.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION Good  
WEATHER CONDITIONS WIND 10-15 SWS 2-3'  
WATERWAY TEMP (°F) SURFACE: 78 MID-DEPTH TO WATER BOTTOM 77

SCREEN WATCH

SCREEN TYPE IN-FLOW X OVER-FLOW \_\_\_\_\_

SCREEN CONTENTS

TRASH mud

BEHIND-SCREEN CONTENTS

SAME

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES \_\_\_\_\_ NO ☒

COMMENTS AND OBSERVATIONS: 1040+00-1000+00

1120 30° 24.398 N 88° 01.021 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?

YES \_\_\_\_\_ NO \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: Kim Peters

OBSERVER'S SIGNATURE Kim Peters

DATA ON TURTLES RETAINED IN HOPPER

SPECIES \_\_\_\_\_

HEAD WIDTH \_\_\_\_\_

PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S. L. LENGTH: \_\_\_\_\_

CARAPACE S. L. WIDTH \_\_\_\_\_

CARAPACE O. C. LENGTH: \_\_\_\_\_

CARAPACE O. C. WIDTH \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: \_\_\_\_\_

DEAD: \_\_\_\_\_

INJURED: \_\_\_\_\_

OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES \_\_\_\_\_ NO \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE \_\_\_\_\_

TURTLE RELEASED WITH TAG? YES \_\_\_\_\_ NO \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT MOBILE channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME STUYVESANT FIRM NAME Bechtel Stuyvesant  
LOAD NUMBER 175 LOADING START TIME (24 HR): 1756 DATE 5.11.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION Good  
WEATHER CONDITIONS WINDS 10-15 Kts SEAS 2-3'  
WATERWAY TEMP (°F) SURFACE: \_\_\_\_\_ MID-DEPTH TO WATER BOTTOM \_\_\_\_\_

SCREEN WATCH

SCREEN TYPE IN-FLOW ☒ OVER-FLOW \_\_\_\_\_

PORT SCREEN CONTENTS

Trash mud + clay

STARBOARD SCREEN CONTENTS

Same

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES \_\_\_\_\_ NO ☒

COORDINATES AND OBSERVATIONS 1040 ± 00 - 1000 ± 00  
H20 30° 24.921 N 88° 01.963 W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES \_\_\_\_\_ NO \_\_\_\_\_

NAME OF SCREEN WATCH OBSERVER: Kim Peters

OBSERVER'S SIGNATURE Kim Peters

DATA ON TURTLES RETAINED IN HOPPER:

SPECIES \_\_\_\_\_

HEAD WIDTH \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH \_\_\_\_\_

SPECIMEN CONDITION ALIVE: \_\_\_\_\_ DEAD: \_\_\_\_\_ INJURED: \_\_\_\_\_ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES: \_\_\_\_\_ NO: \_\_\_\_\_ TAG NO: \_\_\_\_\_

TAG DATE \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: \_\_\_\_\_ NO: \_\_\_\_\_

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W9127804-C-0022  
VESSEL NAME: Stuyvesant FIRM NAME: BEAN Stuyvesant  
LOAD NUMBER: 76 LOADING START TIME (24 HR): 2238 DATE: 5.11.04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO DEFLECTOR CONDITION: GOOD  
WEATHER CONDITIONS: WINDS 10-15 KTS SWS 2-3  
WATERWAY TEMP (°F). SURFACE: 78 MID-DEPTH TO WATER BOTTOM: 77

SCREEN WATCH.

SCREEN TYPE. IN-FLOW ☒ OVER-FLOW ☐

PORT SCREEN CONTENTS: wood, trash, clay, rock

STARBOARD SCREEN CONTENTS: wood, trash, clay, rock

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1040+00-1000+00  
1420 30° 24.40' N 88 01.04' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: no

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: ALICIA L LEFTWICH

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE ☐ DEAD ☐ INJURED ☐ OTHER: \_\_\_\_\_

TURTLE INITIALLY TAGGED? YES ☐ NO ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES ☐ NO ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

2.2.8 Sea Turtle Report Log

SEA TURTLE REPORTING LOG FOR HOPPER DREDGE OPERATIONS

PROJECT: Mobile Channel CONTRACT NO: W91278-01-C-0022  
VESSEL NAME: Starport FIRM NAME: Brace Starport  
LOAD NUMBER: 177 LOADING START TIME (24 HR): 0917 DATE: 5/12/04  
DRAGHEAD DEFLECTOR USED? YES ☒ NO ☐ DEFLECTOR CONDITION: Good  
WEATHER CONDITIONS: Winds 10-15 knots, seas 1-2'  
WATERWAY TEMP (°F): SURFACE: 78 MID-DEPTH TO WATER BOTTOM: 77

SCREEN WATCH.

SCREEN TYPE: IN-FLOW ☒ OVER-FLOW ☐

PORT SCREEN CONTENTS: wood, trash, clay

STARBOARD SCREEN CONTENTS: wood, trash, clay

TURTLE OR TURTLE PARTS PRESENT THIS LOAD? YES ☐ NO ☒

COMMENTS AND OBSERVATIONS: 1040 +00 - 1000 +00  
30° 24.921' N 88° 01.963' W

NAME OF DRAG TENDER AT TIME OF TURTLE TAKE: \_\_\_\_\_

TURTLE PARTS PRESENT IN PORT OR STARBOARD DRAGHEAD: NO

WAS DRAGHEAD TRAILING UNDER HULL OF VESSEL AT TIME TURTLE TAKEN?  
YES ☐ NO ☐

NAME OF SCREEN WATCH OBSERVER: ALICIA L LEFTWICH

OBSERVER'S SIGNATURE: [Signature]

DATA ON TURTLES RETAINED IN HOPPER

SPECIES: \_\_\_\_\_

HEAD WIDTH: \_\_\_\_\_ PLASTRON LENGTH: \_\_\_\_\_

CARAPACE S.L. LENGTH: \_\_\_\_\_ CARAPACE S. L. WIDTH: \_\_\_\_\_

CARAPACE O.C. LENGTH: \_\_\_\_\_ CARAPACE O.C. WIDTH: \_\_\_\_\_

SPECIMEN CONDITION: ALIVE: ☐ DEAD: ☐ INJURED: ☐ OTHER: ☐

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

01431-9 Revised by Amdt DACW01-03-B-0007-0001

TURTLE INITIALLY TAGGED? YES: ☐ NO: ☐ TAG NO: \_\_\_\_\_

TAG DATE: \_\_\_\_\_ TURTLE RELEASED WITH TAG? YES: ☐ NO: ☐

COMMENTS AND OBSERVATIONS: \_\_\_\_\_

01431-9 Revised by Amdt DACW01-03-B-0007-0001